(SUBMIT IN TRIPLICATE)

1

Budget Bureau No. 42-R358.4. Approval expires 12-31-60.

Losse No. 5½ Sec 20, T-31N, R-12W, N.M.P.M., San Juan Unit County, New Mexico

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

SUNDKI NOTICES AN	D REPORTS ON WELLS	
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACTED INF.	r a w c
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OF REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	11 10da
NOTICE OF INTENTION TO PULL OR ALTER CASING.	SUPPLEMENTARY WELL HISTORY	1000
NOTICE OF INTENTION TO ABANDON WELL		50000
	**	GICAL SURVE
(INDICATE ABOVE BY CHECK MARK NA	TURE OF REPORT, NOTICE, OR OTHER DATA)	11, 11211
	October 20	, 19 <u>.59</u>
Well No. 1 Federal/s located 1085 ft. from.	${S \choose S}$ line and 4373 ft. from ${E \choose M}$ line of second	20
SW/4 SW/4 20 31N (Twp.) (Ra	12W N.M.P.M. nge) (Meridian)	ari.
Wildcat San Juan	New Mexico	
(Field) (County or Su	abdivision) (State or Territory)	
	· cont. c.	
he elevation of the derrick floor above sea level	is <u>6074</u> It. NUV	1 8 1959
DETAILS	S OF WORK	4 0 1959 Ом. СОМ
State names of and expected depths to objective sands; show sizes, a ing points, and all other	weights, and lengths of proposed casings; indicate hudding rimportant proposed work)	Sol, cogont-
1. Well was spudded on June 25, 1959 2. Ran 9 jts. 10-3/4*, 32.75*, H-40 landed at 270.93* R.K.B. Bemente	9. surface casing on Jumm 25, 1959. ed with 200 sx reg. cement with 2%	Casing calcium
	00 psi on June 26, 1959. Pressure	held.
4. Ran 85 jts. 7-5/8", 26.40#, J-55	intermediate casing on June 30. 1	959.
Casing landed at 2686' R.K.B. Co	emented with 150 ax reg. cement wi	th 2% gel
5. Drilled plug & pressured up to 50	00 psi on June 31, 1959. Pressure	held.
5. Drilled plug & pressured up to 50	00 psi on June 31, 1959. Pressure	held.
5. Drilled plug & pressured up to 50	00 psi on June 31, 1959. Pressure	held.
Junderstand that this plan of work must receive approval in wri		
I understand that this plan of work must receive approval in wri	ting by the Geological Survey before operations may be com	menced.
I understand that this plan of work must receive approval in wri	ting by the Geological Survey before operations may be com	menced.
I understand that this plan of work must receive approval in wri	ting by the Geological Survey before operations may be com	menced.
I understand that this plan of work must receive approval in wri Company SOUTHERN UNION GAS COMPANY Address 1001 Burt Building	ting by the Geological Survey before operations may be com	menced.
		menced.