| Form 9-331 (May 1963) | DEPART | UNITED STATES MENT OF THE INTER | SUBMIT IN TRIPLICATES (Other instructions on reverse side) | Form approved Budget Bureau 5. LEASE DESIGNATION A | No. #2-R1424. |
|---|---------------------------------------|--|--|--|---------------|
| | · · · · · · · · · · · · · · · · · · · | GEOLOGICAL SURVEY | , | SF-078115 | , |
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) | | | | 6. IF INDIAN, ALLOTTEN | OR TRIBE NAME |
| OIL GAS WELL WE | LL X OTHER | | | 7. UNIT AGREEMENT NAM | E |
| 2. NAME OF OPERATOR | | | | 8. FARM OR LEASE NAME | |
| Aztec Oil & Gas Company 3. ADDRESS OF OPERATOR | | | | Grenier 9. WELL NO. | |
| P. O. Drawer 570, Farmington, New Mexico | | | | #13 | |
| See also space 17 below.) At surface | | | | 10. FIELD AND FOOL OR WILDCAT WEATH | |
| | | 1450' FSL & 1500' FW Section 20-31N-11W | L | 11. SEC., T., R., M., OR BLI SURVEY OR AREA | • |
| 14. PERMIT NO. | | 15. ELEVATIONS (Show whether D | F, RT, GR, etc.) | Section 20-31 | N-11W |
| | | 60 | 29 GR | | New Mexico |
| 16. | Check Ap | propriate Box To Indicate I | Nature of Notice, Report, or O | | <u> </u> |
| | NOTICE OF INTEN | | • | ENT REPORT OF: | |
| TEST WATER SHU | T-OFF | PULL OR ALTER CASING | WATER SHUT-OFF | REPAIRING WE | [v] |
| FRACTURE TREAT | | ULTIPLE COMPLETE | FRACTURE TREATMENT | ALTERING CASI | |
| SHOOT OR ACIDIZE | • | ABANDON* | SHOOTING OR ACIDIZING | ABANDONMENT | |
| REPAIR WELL (Other) | | HANGE PLANS | (Other) | of multiple completion on | |
| (2) S | et Choke @ 5 et Bridge Pl | ug @ 6800'. Found H | oles From 3640'-4700'. | Set Packer @ 3 | 466'. |
| (3) Se | ementea with et Cement Re | 256 Sacks Class "A" tainer @ 2512'. Re- | " Neat With 12½# Gil. Cemented With 250 Sack | s 12k# Gil 2% | CaC1 |
| (4) D. | rilled Out (| ement @ 4328'. Test | ed With 700#. Set Pack | er @ 2481! Com | ontod |
| W. | ith 200 Sack | s Class "A", 125# G | il. 2% CaCl. Pressure | Tested With 100 | Ω# |
| (6) Di | rilled Out O | f Cement @ 4373' P | Cement @ 2818'. Drill ressure Tested To 1000 | ed Cement @ 313 | 2'. |
| (/) C. | leaned Out 1 | o 7169'. Ran 222 Jo | ints Of 2-3/8" Tubing, | Landed @ 7003' | |
| R. | iggea Down. | | , | | • |
| (8) Re | eturned To P | roduction. | PITTON | RECEN | /ED |
| | | Rt | PEIAFD/ | MAY 24 | 1973 |
| | | OIL | (2 5 1973 CON. COM. | U. S. GEOLOGICAL FARMINGTON, | |
| 8. I hereby certify th | at the foregoing is | true and correct | DIST. 3 Strict Superintendent | DATE May 23, | 1973 |
| (This space for Fe | deral or State offic | | | _ DAID | |
| APPROVED BY | | • | | | |
| | APPROVAL, IF AN | TITLE | | DATE | |
| | | | | | |