UNITED STATES BUBMIT IN TRIPLICATE (Other Instructions on reverse side)

5. LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL SURVEY			14-20-604-83
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME Ute Mountain
OIL GAS WELL OTHER			7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR			8. FARM OR LEASE NAME
Benson-Montin-Greer Drilling Corp.			Ute Mountain
3. ADDRESS OF OPERATOR 221 Petroleum Center Building, Farmington, NM 87401			9. WELL NO. #7
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980 FSL, 1980 FWL, Section 21, T-31N, R-14W			10. FIELD AND POOL, OR WILDCAT
			Verde Gallup
			11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA Sec 21, T-31N, R-14W
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)			12. COUNTY OR PARISH 13. STATE
	5626' G R		San Juan New Mexico
16. Check	Appropriate Box To Indicate N	Nature of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO: SUBSEC		WENT REPORT OF:	
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	PULL OB ALTER CASING MULTIPLE COMPLETE ABANDON® CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
operator reques	sts approval of ext	ations and measured and true vertical	

encroachment of water flood water from the west.

APPROVED

DISTRICT OIL & GAS SURERVISOR Vice-President 1980 (This space for Federal or State office use) APPROVED BY ________ CONDITIONS OF APPROVAL, IF ANY: TITLE State

of 31

*See Instructions on Reverse Side