



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078243
Unit A

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

JUN 20 1960

SOUTHERN UNION GOV'T.

June 15, 1960

Well No. 2-19 is located 800 ft. from [N] line and 990 ft. from [E] line of sec. 19

NE 19
(Sec. and Sec. No.)
West Blanco Dakota
(Field)

31N 12W
(Twp.) (Range)
San Juan
(County or Subdivision)

NM
(Meridian)
New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5974 ft. KB

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5/22/60

Ran 3-1/2", 140, 15.50 & 17# casing to 6979'. Cemented through shoe with 225 sacks 6% gel cement. Bump plugs and tested casing to 3000 psi OK. WOC 4 hours, then cemented through stage collar at 4912' with 175 sacks 50% pozmix cement with 12-1/2% gilsonite added. Bump plugs. Pressured up to test sleeve. Casing OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company CONSOLIDATED OIL & GAS, INC.
2112 Tower Building
Address 1700 Broadway
Denver 2, Colorado

By [Signature]
Title Production Manager

