



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 000517
Unit "A"

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 12, 1959

Well No. 5 is located 22 ft. from N line and 204 ft. from E line of sec. 27

27 (1/4 Sec. and Sec. No.) 32 (Twp.) 10 (Range) N.M. (Meridian)
Blanco (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6201 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1. Deepen hole to 6207' u.s.s.
2. Run 2" jts. 5", 15.5, J-55 casing as a liner on October 3, 1959. Pipe landed at 6204' u.s.s. Top of liner at 6111' u.s.s. Ctd. w/75 sx reg. w/4" gel.
3. Squeeze top of liner w/75 sx reg. w/4" gel. on October 4, 1959.
4. Squeeze hole in 7" cas. at 2205' w/50 sx reg. cement on October 6, 1959.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SANTA FE OIL COMPANY

Address P.O. Box 115

Farmington, New Mexico

By Ternon J. Lowe

Title Drilling Superintendent