

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office San Antonio, Tex.  
Lease No. 10028  
Unit San Antonio 32-1 Unit  
14-0-001-56

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 100 is located 1000 ft. from S line and 100 ft. from W line of sec. 10  
in Sec. 10 (1/4 Sec. and Sec. No.) 10 (Twp.) 10 (Range) 10 (Meridian)  
Blanco (Field) San Antonio (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 1000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud date 5-27-51.  
on 5-28-51. Total depth 170'.  
Run 4 joints, 10 3/4", 32.15', spiral well casing (162') set at 1/2' with  
200 sacks regular cement, w/20 Gall. circulated to surface.  
Held 600/30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Antonio Natural Gas Company  
Address Box 30  
Farmington, New Mexico  
By Original Signed D. C. Johnston  
Title retired engineer