

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office
Lease No.
Unit

71-01-001-946

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 11, 1956

Well No. 3-1 is located 1139 ft. from N line and 1109 ft. from E line of sec. 3


24 Sec. and Sec. No. 324 (Twp.) 11 (Range) N. 100.000 (Meridian)
Blanco (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6577 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled to 57.5', set 57.3' of 3" x 11.55 3-55 casing w/ Baker float shoe - 57.5' and cemented w/ 200 lb of reg. cement w/ 8-4 added. 5-23-56. 5-25-56 and rig released a 5:30 p.m. 5-25-56. Moved on completion rig. 5-25-56 for 3 hours, casing tested o.k. Prepared to perf. and free well.



I understand that this plan of work must receive approval in writing by the Geological Survey before operation may be commenced.

Company Arctic Slope Drilling Co., Inc.

Address 1111 N. 1st St., Fairbanks, Alaska

By Original signed by T. A. Dugan

Title District Engineer