

PAN AMERICAN PETROLEUM CORPORATION

<u>DEPTH</u>	<u>DEVIATION</u>	<u>DEPTH</u>	<u>DEVIATION</u>
90	0°	2060	4°
150	0°	2187	3 1/4°
240	1/4°	2333	3°
394	1/4°	2395	2°
559	1°	2465	2°
716	2 1/2°	2574	2°
779	2 1/2°	2770	1 1/4°
842	2 3/4°	3077	1°
905	3°	3311	1/2°
965	3°	3744	3/4°
1059	3°	3927	3/4°
1119	3°	4061	3/4°
1182	3°	4613	1/4°
1240	3 1/2°	4896	1/4°
1312	2 3/4°	5330	3/4°
1373	3°	5402	1°
1530	3°	6111	3/4°
1590	3°	6531	3/4°
1688	3 1/2°	7040	3/4°
1750	3 1/4°	7366	1°
1810	3 1/4°	7620	1 1/2°
1876	3 1/4°	7900	2°
1936	3 1/4°	8109	1 1/4°

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation test taken on PAN AMERICAN PETROLEUM CORPORATION'S **Ute Mountain Tribal "H" Well #1, 2170 FSL, 1650 FWL, Section 1, T31N, R14W, San Juan County, New Mexico.**

ORIGINAL SIGNED BY
D. I. TOLLEFSON

Signed _____
Title **Administrative Assistant**

BEFORE ME, the undersigned authority, on this day personally appeared D. I. Tollefson known to me to be Administrative Assistant for Pan American Petroleum Corporation and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.

SUBSCRIBED AND SWORN TO before me, a Notary Public in and for
said County and State this **9th** day of **February**, 1966.

Harold A. Kapt
Notary Public

My Commission Expires: June 2 1969

