

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELL MANAGEMENT

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER OCT 31 1985

2. NAME OF OPERATOR
Benson-Montin-Greer Drilling Corp. Durango, Colorado

3. ADDRESS OF OPERATOR
221 Petroleum Center Building, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1650' FSL, 660' FEL, Sec. 29, T31N, R14W

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
5544' GR

5. LEASE DESIGNATION AND SERIAL NO.
14-20-604-1939

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Ute Mountain Tribal

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Ute Mountain Tribal 1939

9. WELL NO.
#14

10. FIELD AND POOL, OR WILDCAT
Verde Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 29, T31N, R14W

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☒
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☒
(Other) ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

09/24/85 thru 10/21/85

Cement plug #1 - 4600' to 4300' (estimated) with 30 cubic feet (25 sacks) cement slurry.

Cement plug #2 - 2425' to 2248' (estimated) with 23.60 cubic feet (20 sacks) cement slurry.

Shot off 4-1/2" casing 1702'. Pulled 4-1/2" casing.

Cement plug #3 - 1702' to 1576' (estimated) with 41.30 cubic feet (35 sacks) cement slurry. Plug failed, ran in hole with 2-3/8" EUE tubing and did not find cement.

Cement plug #3 - 1806' to 1500' with 61.36 cubic feet (52 sacks) cement slurry. Cement plug located at 1500' by running in hole with 2-3/8" EUE tubing.

Cement plug #4 - 181' to surface (estimated) with 61.36 cubic feet (52 sacks) cement slurry. Bureau of Land Management Representative, Jack Kaiser, Petroleum Engineer Technician, on location to witness cementing of plug #4 and measuring down to plug #3.

Set and cemented dry hole marker. Cleaned up location. Well permanently plugged and abandoned.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Vice President

DATE 10/30/85

(This space for Federal or State office use)

APPROVED BY L. Mark Hollis

TITLE ACTING AREA MANAGER

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
AS AMENDED

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully United States any false, fictitious or fraudulent statements or representations as to an

APPROVED TO THE PLUGGING OF THE WELL BORE ONLY. LIABILITY UNDER THE BOND RETAINED UNTIL SURFACE RESTORATION IS COMPLETED AND APPROVED.