



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa Fe
Lease No. 072297
Unit Horton

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Water Frac.</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 30, 1960

Well No. 28 is located 500 ft. from N line and 900 ft. from E line of sec. 26
N.E. 28 31 N 11 W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco N.V. & Wildcat Dakota San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

6-22-60 Total Depth 7150. C.O.T.D. 7000. Water fractured Lower Dakota, perforated intervals 6998-7006; 7012-7026; 7032-7038; 7046-7060 w/2 DJ/ft. with 40,200 gal. water and 40,000 # sand. Breakdown pr. 2500 #, max. pr. 3500 #, avg. tr. pr. 3200-3300-3400-3500 #. I.R. 30.5 B.P.M. Flush 2240 gallons.
6-23-60 Temporary Bridge Plug at 6980. Water fractured Upper Dakota & Graneros perforated intervals 6814-6822; 6830-6835; 6844-6856; 6870-6878; 6904-6912 w/2 DJ/ft. with 40,300 gal. water and 40,000 # sand. Breakdown pr. 1200 #, max. pr. 3500 # avg. tr. pr. 2400-2500-2600-3400 #. I.R. 43.5 B.P.M. Flush 3,400 gallons.
6-27-60 Temporary Bridge Plug at 5500. Water fractured Point Lookout perf. int. 4772-4774; 4782-4784; 4794-4806; 4810-4818; 4820-4828; w/2 DJ/ft. with 46,200 gal. water and 40,000 # sand. Breakdown pr. 600 #, max. pr. 2500 #, avg. tr. pr. 1000-2200-2500-3500 #. I.R. 60.1 B.P.M. Flush 5040 gallons

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas CompanyAddress Box 930Farmington, New MexicoBy ORIGINAL SIGNED H.E. MORRISTitle Petroleum Engineer