

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well  gas well  other

2. NAME OF OPERATOR  
AMOCO PRODUCTION COMPANY

3. ADDRESS OF OPERATOR  
501 Airport Drive Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
1650' FSL x 1800' FEL, Section 11,  
AT SURFACE: T-31-N, R-14-W  
AT TOP PROD. INTERVAL: Same  
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input checked="" type="checkbox"/>
(other)	<input type="checkbox"/>		<input type="checkbox"/>

5. LEASE  
14-20-604-78

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
Ute Mountain Tribe

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Ute Mountain Tribal "J"

9. WELL NO.  
3

10. FIELD OR WILDCAT NAME  
Ute Dome-Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
NW/4 SE/4 Section 11,  
T-31-N, R-14-W

12. COUNTY OR PARISH  
San Juan

13. STATE  
NM

14. API NO.  
30-045-21179

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
5781' GL, 5795' KB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*  
Abandonment operations commenced on 9/19/78. Pulled rods and pump. Pulled tubing to 2856'. Spotted 26 sx Class "B" cement 2860-2630'. Pulled tubing to 2150' and spotted 46 sx cement 2150-1750'. Pulled tubing to 340' and spotted 10 sx cement 340-260'. Pulled tubing and spotted 10 sx plug 62' - surface. Hooked up to bradenhead and tried to squeeze annulus would not take cement. Cut off well head and erected P & A marker. Moved out service unit and cleaning up location. Operations completed on 9/20/78.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED E. E. SVOBODA TITLE District Adm. Supvr DATE 10/04/78

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
 OCT 5 1978  
 U. S. GEOLOGICAL SURVEY  
 DURANGO, COLO.

\*See Instructions on Reverse Side