

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

JUL 11 1990

Sundry Notices and Reports on Wells

OIL CON. DIV.,
DIST. 3

1. Type of Well
GAS

2. Name of Operator
Southland Royalty Company

3. Address & Phone No. of Operator
Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec, T, R, M.
1840'N, 1110'W Sec. 1, T-31-N, R-12W, NMPM

5. Lease Number
SF-077648

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number
Davis #19

9. API Well No.

10. Field and Pool
Basin Fruitland Coal

11. County and State
San Juan County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA
Type of Submission

Notice of Intent
 Subsequent Report
 Final Abandonment

Type of Action
 Abandonment
 Recompletion
 Plugging Back
 Casing Repair
 Altering Casing
 Other

Change of Plans
 New Construction
 Non-Routine Fracturing
 Water Shut Off
 Conversion to Injection

13. Describe Proposed or Completed Operations

06-09-90 MOL&RU. Blow down. Kill well w/15 bbl. 2% KCl wtr. Ran GR-CBL-CCL 2900-2450'. TOC @ 1800'. Set CIBP @ 2875'. SD for weekend.

06-10-90 NU BOP. TIH w/tbg & pkr, found hole in csg between 106-139'. Test below pkr set @ 139 to 2500#/15 min, ok. POOH. ND BOP. PU on 2 7/8" csg. Back off @ 135'. Pull 4 jts. TIH, screw into 2 7/8", back off @ 166'. LD bad csg & replace. PT would not hold. Back off @ 197'. Pull bad pipe. TIH w/new pipe. Screw into 2 7/8" csg. PT 2400#, broke down & circ out bradenhead. Back off @ 343'. POOH, small split @ 210'. Replace all bad pipe. TIH, PT would not hold. Back off @ 464'. Holes @ 430' & 450'. Replace bad pipe. Screw into csg, PT 3500#/15 min, ok. SDFN. (cont'd on back)

14. I hereby certify that the foregoing is true and correct

Signed [Signature] Title Regulatory Affairs Date 6-19-91

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY _____ TITLE _____
CONDITION OF APPROVAL, IF ANY:

JUL 06 1990
DATE

FARMINGTON RESOURCE AREA

BY [Signature]

- 06-12-90 NUWH. Run perf gun to 430', no go. Run 1 1/4" tbg to 600' & circ hole clean. TOOH. PT csg 2500#, ok. Perf 2650-60', 2746-66', 2790-96', 2826-35', 2858-60' w/2 spf. BD perfs w/960 gal. 7.5% HCl. Swabbed well. SI. SDFN.
- 06-13-90 Frac w/7740# 40/70 sand, 120,520# 20/40 sand, 2277 BW and x-link gel. Flow well back and SI. SDFN.
- 06-14-90 TIH, blow down w/air. Ran tbg to 2868', tag fill. CO to btm of 2875' w/air. Pull above perfs, blow w/air. SDFN.
- 06-15-90 TIH, tag fill @ 2865'. CO to 2875'. Blow w/air. SD for weekend.
- 06-16-90 Unload well. TIH w/tbg, tag BP @ 2875'. No fill. Blow well. Ran 89 jts 1 1/4", 2.33#, J-55 IJ tbg set @ 2845'. SN @ 2812'. Released rig.

ABTD 2875
Temp.
Abandoned PC