

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

91 MAY 17 AM 7:51

5. Lease Number

SF-078244

6. If Indian, All or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number

Taliaferro #3E

9. API Well No.

10. Field and Pool

Basin Dakota

11. County and State

San Juan County, NM

1. Type of Well
GAS2. Name of Operator
Meridian Oil Inc.3. Address & Phone No. of Operator
Box 4289, Farmington, NM 87499 (505) 326-97004. Location of Well, Footage, Sec, T, R, M.
900'S, 1735'E Sec. 31, T-31-N, R-12-W, NMPM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent☐ Abandonment☐ Change of Plans☒ Subsequent Report☐ Recompletion☐ New Construction☐ Final Abandonment☐ Plugging Back☐ Non-Routine Fracturing☐ Casing Repair☐ Water Shut Off☐ Altering Casing☐ Conversion to Injection☒ Other - P&A MV

13. Describe Proposed or Completed Operations

- 11-05-83 MOL&RU. Kill Dakota w/20 BW. ND WH. NU BOP. Could not release pkr. Circ wtr thru sliding sleeve. SDFN.
- 11-06-83 Made chem. cut 3' above sleeve. TOOH w/tbg. TIH w/overshot, grapple, sub & jars, tag sand 4' above fish. CO w/N2. Latch onto fish, work pkr loose. Pull up to 3500'. SD for weekend.
- 11-08-83 TOOH, no pkr. Set RBP @ 5012'. PB 2000#, ok. Spot 10 gal. sand on RBP, pull RTTS to 4330' to squeeze perms @ 4546-4739'. PT, leak thru pipe rams. Pull tool up to 2500', still leak. Reset RTTS @ 4330'. Cmt'd w/100 sx Class "B" cmt w/2% calcium chloride, 0.6% FLA, tailed w/100 sx Class "B" w/2% calcium chloride. Held 2000#. Release press., did not flow back. TOOH w/RTTS. SDFN.
- 11-09-83 TIH w/RTTS to 2000'. PT 2000#, ok. Pump into backside. Found 6' gap @ 486' @ collar. SDFN.
cont'd on back

14. I hereby certify that the foregoing is true and correct

Signed Penny Shalinski Title Regulatory Affairs Date 5-14-91

ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

DATE _____

CONDITION OF APPROVAL, IF ANY:

FARMINGTON, NM 87401

SM

N14000

Taliaferro #3E, cont'd.

11-10-83 Set EZ Drill @ 466'. Pumped into tbg. Cmt'd w/100 sx Class "B" w/10# cal seal/sx & 10% salt. Stung out of EZ Drill. TOO. WOC. SDFN.

11-11-83 TIH, tag cmt @ 456'. Drld cmt. Drld thru EZ Drill. SDFN.

11-12-83 Drld thru tool @ 500'. PT 1000#/15 min, ok. Trip to 4000'.

11-13-83 TIH, tag cmt @ 4335'. Drld cmt to 4745', fell through. Circ clean. PT 1000#/15 min, ok. TIH to 5000'. Clean sand off RBP @ 5012'. SD for weekend.

11-15-83 TIH, unable to latch onto RBP. TIH w/washover shoe. Wash 20" cmt, fill from FBP. TIH, retrieve BP. TOO to 4000'. SDFN.

11-16-83 Full BP. Run wash pipe. Wash w/wtr & N2. TOO. SDFN.

11-17-83 Ran overshot, sub, jars & collars. Jar on pkr. Made 10". SDFN.

11-18-83 Jar pkr loose & TOO. LD fish & tools. SDFN.

11-19-83 TIH, CO to 6904'. Land 221 jts 2 3/8" tbg @ 6865'. SN 1 jt off btm. ND BOP. NU WH. Kick well off. SDFN.

11-20-83 Swabbed. SD for weekend.

11-22-83 Swabbed. Kicked off. Flow to pit. Released rig.

NOTE: This work done by Union Texas Petroleum in 1983.