

State of New Mexico Energy, Minerals and Natural Resources Department

SUBMIT I COPY TO APPROPRIATE DISTRICT OFFICE AND I COPY TO SANTA FE OFFICE

OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088

ONLY PIT REMEDIATION AND CLOSURE REPORT

for formation and a secretar section and a secretary and a section of the section				
Operator: Phillips Petroleum Company		Telephone: (505) 599-3462_	
Address: 5525 Hwy. 64, NBU 3004, F	armington, NM	87401		
Facility Or: San Juan 32 - 7 Unit # 75 Well Name	<u> </u>			
Location: Unit or Qtr/Qtr Sec_SWSW_Sec27	T_32N	R 7W County Sar	n Juan	
Pit Type: Separator X	Dehydrator	Other		
Land Type: BLM X,	State,	Fee, Other	r	
Pit Location: Pit dimensions: L (Attach diagram) Reference wellhea	ength <u>17 ft</u>			
Footage from referen	ce: <u>55 ft</u>			
Direction from refere	ence:60	DegreesX Ea	ast North	
		West	South X	_
Depth to Ground Water: 100 ft		Less than 50 feet 50 ft to 99 ft	(20 points)	
contaminants to seasonal nighwater elevation of ground water)	EN	Greater than 100 feet	· -	10
Wellhead Protection Area: Cless than 200 feet from a private domestic water source, or: less than 1000 feet from all other water source.		Yes X_ No	(20 points) (0 points)	0
Distance to Surface Water: Horizontal distance to perennial		Less than 200 feet 200 feet to 1000 feet	(20 points) (10 points)	0
akes, ponds, rivers, streams, creeks, rrigation canals and ditches.)	_X_	Greater than 1000 feet	(0 points)	0
P:\pits\PrrC@.WK3	RANI	KING SCORE (TOTAL I	POINTS):	10

	n Started: $\frac{7/}{}$	8/94		Dated Completed: _	10/14/94
	Excava	tion <u>X</u>	· ·	Approx. cubic yards	38
	Landfar	med <u>X</u>		Insitu Bioremediatio	on
	Other _				
	-				
Remediation Method:	Onsite _	X	Offs:	te	
(Check all appropriate			-	<u> </u>	
sections)					
General Description of Rer NMOCD and BLM (The pit after excavate Assessment was perful pit closure informatrical NMOCD and BLM (State of the pit no risk to human state of the pit of the p	Guidelines. The ion was determined utilizing ion. The landfaguidelines. Base	e pit was ined to b the prev rm was s ed on thi	excavated to be outside NM rious pit asses sampled on 10 is information	bedrock (7 feet belood bedrock (7 feet belood bedrock) Sment and is enclosed by 14/94 and was four	ow ground level). idelines and a Risk ed with subsequent and to be within
Ground Water Encountered	l: No	X	Ye	s Dep	th
Final Pit: Closure Sampling (if multiple samples.	Sample location _S	See pit cl	osure & risk	assessment reports_	
attach sample results	~ · · · · 7	1 11			
attach sample results and diagram of sample locations and depths)	Sample depth7				
attach sample results and diagram of sample locations and depths)	Sample depth $\frac{7}{2}$				e time _10:40
attach sample results and diagram of sample locations and depths)					e time _10:40
attach sample results and diagram of sample locations and depths)	Sample date	29/94			e time <u>10:40</u>
attach sample results and diagram of sample locations and depths)	Sample date 7/ Sample Results Benzene(1	29/94 opm)			e time <u>10:40</u>
attach sample results and diagram of sample locations and depths)	Sample date 7/ Sample Results Benzene() Total BTE	29/94 opm) EX (PPM)	ND		e time <u>10:40</u>
attach sample results and diagram of sample locations and depths)	Sample date 7/ Sample Results Benzene() Total BTE	ppm) EX (PPM) dspace (pp	ND 55.68 m) 873		e time <u>10:40</u>
attach sample results and diagram of sample locations and depths)	Sample date 7/ Sample Results Benzene() Total BTE	29/94 opm) EX (PPM)	ND 55.68 m) 873		e time <u>10:40</u>

Risk Assessment San Juan 32-7 #75

Depth to Groundwater	100'
Distance to Water Source	>1000'
Distance to Surface Water	>1000'
TPH Limit (ppm)	1000


The subject pit was located in silty sand with clay soil. The initial size of the pit was $15' \times 15' \times 4'$ deep. The stained soil was excavated to a final pit size of $17' \times 17' \times 7'$ deep, where bedrock was encountered. Excavated soil amounted to 38 total cubic yards, and was landfarmed on location.

The excavation was assessed by Envirotech on 7/8/94. Two test holes were utilized for assessment. The test holes were established in the center of the pit with a total depth of 7 feet and approximately 10 feet west of the pit (down gradient) to a depth of 4 feet. Both test holes encountered hard bedrock at 7 and 4 feet respectfully. Headspace analysis of the test holes revealed a concentrations ranging from 800 parts per million (ppm) to 770 ppm and TPH levels from 5720 ppm to 352 ppm. Test Hole # 2 was evaluated for BTEX concentrations and results provided a Benzene concentration of 0.028 ppm and a Total BTEX concentration of 9.32 ppm, both results within NMOCD and BLM Guidelines. Excavation of the walls and bottom was performed on 7/29/94. The excavation proceeded to a depth of 7 feet (bedrock). Headspace analysis of the walls and bottom showed OVM levels ranging from 873 ppm to 669 ppm, and a TPH level of 996 ppm, utilizing EPA Method 418.1. A sample from the east wall, bedrock, (873 ppm: Headspace) was analyzed for Benzene, Toluene, ehtyl Benzene, and Xylene (BTEX) utilizing EPA Method 8020. Results of the analysis provided concentrations outside NMOCD and BLM guidelines (Benzene = non-detect, Total BTEX = 55.68 ppm). The landfarm was tested on 10/14/94 by Envirotech and was found to be within closure guidelines (TPH = 339 ppm, Benzene = non-detect and a Total BTEX concentration of 1.10 ppm).

No groundwater was encountered, and first water was not recorded on the nearby cathodic well until a depth of 100 feet.

Having established vertical extent, hard bedrock at a depth of 7 feet below ground level, the pit being encased on bedrock, and a test hole (#2 on assessment) having achieved action levels below NMOCD and BLM requirements this pit should be considered to have reached "final closure". Phillips Petroleum has removed and remediated all soils to the extent practical. By filling the excavation, the driving force created by additional fluids will be eliminated. Based on this information and the physical location of the pit, there is little to no risk to human health or environment.

ENVIROTECH Inc. PIT NO: PA 217 5796 US HWY 64, FARMINGTON, NM 87401 (505) 032-0615 C.O.C. 110: 3675 JOB No. _ 93163 FIELD REPORT: SITE ASSESSMENT PAGE No: DATE STARTED: PROJECT. PHILIPS PETIOLEUM DATE FRAISHED: 7/8/94 ELIMARO, SPOLT: CLG CLIENT CONTRACTOR _ENVIROTECH_INC. EQUIPMENT_USED: _Case Extend-a-dig OPERATOR: Cimarron ASSISTANT: KG QI) 970' FSL, 860' FEL (P) LOCATION: LEASE: San Juan 32-7 WELL: 75 l'ITSep./Prod. STMM SEC: 27 TWP:32N RNG7W I.W. WW CNTYSJ Range - Lease # SF-078543 Elv. 6732' LAND USE: Dry earthen pit; not stained SURFACE CONDITIONS: PIT CENTER IS LOCATED APPROXIMATELY 55 FEET \$60E OF WELLHEAD. CLOSURE STD: 1,000 ppm GW = 100' RANKING SCORE: 10 T1: Dark gray sand with silt and moist clay (moderately plastic in some areas. 7' became rocky and couldn't excavate further. Water is entering excavation (~ 6' BGS) - has yellowish tint. T2: Light grey compact sand and dry silt.; rock @ 4' TEST HOLE LOGS T11# SOIL SUPL COUP SHE SUPE CONT SAMPLE INVENTORY SONE SHIPE CANT SOIL SUPL ONV/ ANALYSIS SKITI. ID SMP1. T1@7' Soil dilute 28.6x1 0=5720ppm 2 T2@4 Soil 418.1 3 176x2=352ppm SCALE SM/GR# 800 T2@4' Soil BTEX Pit bottom 4 FEET 5 Rock TD=4 SITE DIAGRAM SC **G**RB|770 Production tank Rock TD=7 8 9 Berm 10 11 12 13 Separator To well head & 14 Surface Gradient



5796 US Highway 64-3014 • Farmington, New Mexico 87401 PHONE: (505) 632-0615 • FAX: (505) 632-1865

FIELD MODIFIED EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:

Phillips Petroleum

Project #:

93163

Sample ID:

T1 @ 7'

Date Analyzed:

7-8-94

Project Location:

San Juan 32-7 #75

Date Reported:

7-8-94

Laboratory Number:

GAC0601

Sample Matrix:

Soil

Parameter

Result, mg/kg

Detection Limit, mg/kg

Total Recoverable

Petroleum Hydrocarbons

5,720

100

ND = Not Detectable at stated detection limits.

QA/QC:

QA/QC Sample TPH mg/kg _____

Duplicate TPH mg/kg %

11,000

12,600

*Diff.

14

*Administrative Acceptance limits set at 30%.

Modified Method 418.1, Petroleum Hydrocarbons, Total

Recoverable, Chemical Analysis of Water and Waste,


USEPA Storet No.4551, 1978

Comments:

Method:

Separator/Production Pit

PA217



5796 US High-way 64-3014 • Farmington, New Mexico 87401 PHONE: (505) 632-0615 • FAX: (505) 632-1865

FIELD MODIFIED EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:

Phillips Petroleum

93163

Sample ID:

T2 @ 4'

Project Location:

San Juan 32-7 #75

7-8-94 7-8-94

Laboratory Number:

GAC0602

Date Reported: Sample Matrix:

Date Analyzed:

Project #:

Soil

Parameter

Result, mg/kg

Detection Limit, mg/kg

Total Recoverable

Petroleum Hydrocarbons

352

10

ND = Not Detectable at stated detection limits.

QA/QC:

QA/QC Sample TPH mg/kg

Duplicate TPH mg/kg %

*Diff.

11,000

12,600

14

Method:

Modified Method 418.1, Petroleum Hydrocarbons, Total

Recoverable, Chemical Analysis of Water and Waste,


USEPA Storet No.4551, 1978

Comments:

Separator/Production Pit

PA217

^{*}Administrative Acceptance limits set at 30%.



5796 US Highway 64-3014 • Farmington, New Mexico 87401 Phone: (505) 632-0615 • Fax: (505) 632-1865

EPA METHOD 8020 AROMATIC VOLATILE ORGANICS

Client:	Phillips	Project #:	93163
Sample ID:	T2 @ 4'	Date Reported:	07-15-94
Laboratory Number:	7708	Date Sampled:	07-08-94
Sample Matrix:	Soil	Date Received:	07-08-94
Preservative:	Cool	Date Extracted:	07-08-94
Condition:	Cool,& Intact	Date Analyzed:	07-14-94
	4	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)
Benzene	28	26.8
Toluene	477	33.5
Ethylbenzene	424	20.1
p,m-Xylene	5670	26.8
o-Xylene	2720	20.1

SURROGATE RECOVERIES:	Parameter	Percent Recovery
	Trifluorotoluene	116 %
	Bromofluorobenzene	112 %

Method:

Method 5030, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA, July 1992

Method 8020, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, Sept. 1986.


ND - Parameter not detected at the stated detection limit.

Comments: San Juan 32-7 #75 Sep/Prod Pit PA217.

Review Review

17217		Remarks	C	40 pod. p. t			-			7-8-94 1516			san juan rapro Form 678-41
4	ANALYSIS/PARAMETERS		ď	37	-		-			82		-	
N OF CUSTODY RECORD		to to X3		\	-/				ture)	Karen your	Received by: (Signature)	Received by: (Signature)	CH INC. way 64-3014 Mexico 87401 -0615
CHAIN OF CUST	32-7 #75	V	Sample Matrix	(ios					Date Time R	0121 PASIC	<u>«</u>	E	ENVIROTECH INC. 5796 U.S. Highway 64-3014 Farmington, New Mexico 87401 (505) 632-0615
S	Project Location San Juan 32-7	Chain of Custody Tape No.	Lab Number	2011									
	-		Sample Time	0111	:								
	93163		Sample Date	7/8/94									
		Sampler: (Signature)	Sample No./ Identification	72 @ 4'					Relinquished by: (Signature)	Clark	Relinquished by: (Signature)	Relinquished by: (Signature)	

CLIENT: Phillips Petroleum ENVIROTECH Inc.	PIT NO: PA 217					
5798 US HWY 64, FARMINGTON, NM 87401 (505) 632-0815	C O C. NO 3693					
FIELD REPORT: CLOSURE VERIFICATION	JOB No: <u>93163</u> FAGE No: <u>1</u> of <u>1</u>					
LOCATION: NAME: San Juan 32-7 WELL #75 Pricep./prod. QUAD/UNIT: P SEC: 27 TWP32N RNGW BMM CNTQJ NM	DATE STARTED:					
QTR/FUUTAGE: CONTRACTOR: Cimarron	ENVIRONIMENTAL SPECIALIST: <u>CLG</u>					
SOIL REMEDIATION: EXCAVATION APPROX. 17 FT. x 17 FT. 7x DISPOSAL FACILITY: Landfarmed on-site CUBIC YARI						
LAND USE Range LEASE: SF-078543						
FIELD NOTES & REMARKS: PIT LOCATED APPROXIMATELY 55 FEET SOE FROM WELLHEAD. BEPTH TO GROUNDWATER: 100' NEAREST VATER SOURCE: >1000 NEAREST SURFACE VATER: >1000						
NHOCD RANKING SCORE: 10 NHOCD TPH CLOSURE STD 1000 PPM						
SOIL AND EXCAVATION DESCRIPTION:						
Bottom of excavation is rock. Sides are gray clay and sand, cohesive, slightly mois	t.					
FIELD 4181 CALCULATIONS						
SAMPLE LD. LAB No: WEIGHT (g) I'L FREON DILUTION READING CALC	ppm					
2@6' 622 10 20 1 498 996						
SCALE						
SCALE A						
O FEET OVM PIT PERIMETER N PERIME	PROFILE					
171 17 LIKIMETEK IN RESULTS 1711	I ROFILE					
Production Tank	_					
3 S 3@6' 861						
5 CB 5@7 662						
						
LAR SAMPLES	Rock -					
To Songrator 2@6' BTEX						
Separator - Well Head						
TRAVEL NOTES: CALLOUT: 7/29/94 ONSITE: 7/29/94						



5796 US Highway 64-3014 • FARMINGTON, New Mexico 87401 Phone: (505) 632-0615 • FAX: (505) 632-1865

FIELD MODIFIED EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:

Phillips Petroleum

93163

Sample ID:

2@6'

Project #:
Date Analyzed:

7-29-94

Project Location:

San Juan 32-7 #75

Date Reported:

7-29-94

Laboratory Number:

GAC0622

Sample Matrix:

Soil

Parameter

Result, mg/kg

Detection Limit, mg/kg

Total Recoverable

Petroleum Hydrocarbons

996

10

ND = Not Detectable at stated detection limits.

QA/QC:

QA/QC Sample TPH mg/kg Duplicate

%

TPI

TPH mg/kg

*Diff.

11,000

12,600

14

*Administrative Acceptance limits set at 30%.

Method:

Modified Method 418.1, Petroleum Hydrocarbons, Total

Recoverable, Chemical Analysis of Water and Waste,

USEPA Storet No.4551, 1978

Comments:

Separator/Production Pit

PA217

Analyst


Review Journa

CHAIN OF CUSTODY RECORD

sepland. pit	\ 	8.	7754		7/24/94 1040	(2) e 6'
	BT	Sample Matrix	Lab Number	Sample Time	Sample Date	Sample No./ Identification
	o. of tainers					agunta
Remarks		No.	Chain of Custody Tape No.			Sampler: (Signature)
	ANALYSIS/PARAMETERS	San Juan 32-7 #75	San Ilan		93/63	Phillips (
			Project Location			Pliant/Draigat Name

ENVIROTECH INC. 5796 U.S. Highway 64-3014 Farmington, New Mexico 87401

(505) 632-0615



5796 US Highway 64-3014 • Farmington, New Mexico 87401 Phone: (505) 632-0615 • Fax: (505) 632-1865

EPA METHOD 8020 AROMATIC VOLATILE ORGANICS

Client:	PHILLIPS	Project #:	93163
Sample ID:	2@6'	Date Reported:	08-10-94
Laboratory Number:	7756′	Date Sampled:	07-28-94
Sample Matrix:	Soil	Date Received:	07-28-94
Preservative:	Cool	Date Analyzed:	08-10-94
Condition:	Cool & Intact	Date Extracted:	08-10-94
		Analysis Requested:	BTEX

Parameter	Concentration (ug/L)	Limit (ug/L)
Benzene	ND	13.1
Toluene	3750	13.1
Ethylbenzene	9670	13.1
p,m-Xylene	2760	13.1
o-Xylene	39500	13.1

SURROGATE RECOVERIES: Parameter Percent Recovery
-----Trifluorotoluene 122 %
Bromfluorobenzene 135 %

Method: Method 5030, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA, Sept. 1986

Method 8020, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, Sept. 1986


ND - Parameter not detected at the stated detection limit.

Comments: SAN JUAN 32-7 # 75 SEP/PROD PIT PA217

EXCESSIVE SURROGATE RECOVERIES DUE TO COELUTION

Rot & Haiffin inalyst Review Review

<u></u>		•	
	ENVIROTEC 5796 US HWY. 64, FARM (505) 632-0	AINGTON, NM 87401	PIT No: <u>PA217</u> c.o.c #:_3859
FIELD REPORT:	REMEDIATION F. CLOSURE VERIF		JOB No:93163 PAGE No: _1 of 1
FACILITY LOCATION: San Juan 32-7 # SOURCE LOCATION: SOURCE LOCATION:			DATE STARTED: 10/14/94 DATE FINISHED: 10/14/94
SOURCE LOCATION:Outside Lar	ndfarm Pi	TYPE:	ENVIRONMENTAL CJG
SOIL REMEDIATION: QUANTITED DIMENSION VISIBLE OBSERVATION SAMPLING PLAN:	s 27' x 30' x 1'	,,,,,	F COMP. SAMPLES.1
FIELD NOTES & REMARKS; FA	CILITY CENTER LOCATE	D APPROX 38 YARDS	NE FROM WELLHEAD.
DEPTH TO GROUNDWATER: NEAREST WATER SOURCE/TYPE: NEAREST SURFACE WATER: MAX TPH PER NMOCD: NO. OF 5-POINT COMPOSITE SAMPLES: YAPDAGE == # 0-200=1 201-400=2 401-1000=3 >1000=5	#840 C1: 20ml x 1 x 2	52 =508 ppm TPH	•
FACILITY DIAGRAM	GRID SCALE: 1	" = 20'	
+ + +	· · ·	OVM RESUL	TS
+ + ×	, + +	C1 339	
C1 + X	*		NORTH
X	× + +		WELLHEAD
+ + +	+ + +	LAB RESUL* + SAMPLE MALISIS 10: RECORSTED	rs
+ + +	+ + +	C1 TPH C1 BTEX	508 SURFACE FLOW DIR.
+ + +	· • • •		
			GROUNDWATER FLOW DIR.



5796 US HIGHWAY 64-3014 • FARMINGTON, NEW MEXICO 87401 PHONE: (505) 632-0615 • FAX: (505) 632-1865

FIELD MODIFIED EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:

Sample ID:

Project Location: Laboratory Number: Phillips Petroleum C1-LANDFARM

San Juan 32-7 # 75

GAC0840

Project #:

Date Analyzed:

Date Reported:

Sample Matrix:

93163

10-14-94

10-17-94

Soil

Parameter	Result, mg/kg	Detection Limit, mg/kg				
Total Recoverable Petroleum Hydrocarbons	508	10				

ND = Not Detectable at stated detection limits.

QA/QC:

QA/QC Sample TPH mg/kg

98 *

Duplicate

TPH mg/kg

96

%

*Diff.

1

*Administrative Acceptance limits set at 30%.


Method:

Modified Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water and Waste,

USEPA Storet No.4551, 1978

Comments:

Separator Pit PA217



5796 US HIGHWAY 64-3014 • FARMINGTON, NEW MEXICO 87401 PHONE: (505) 632-0615 • FAX: (505) 632-1865

EPA METHOD 8020 AROMATIC VOLATILE ORGANICS

Client: Sample ID: Laboratory Number: Chain of Custody Sample Matrix: Preservative: Condition:	Cl landfarm 7976BTEX. 3959 Soil Cool Cool & Intact	Project #: Date Reported: Date Sampled: Date Received: Date Extracted: Date Analyzed: Analysis Requested:	93163 11-03-94 10-14-94 10-14-94 10-21-94 11-02-94 BTEX
Condition:	COOL & INCACE	mariors medacases	

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)		
	ND	13.2		
Benzene	88	26.4		
Toluene	48	13.2		
Ethylbenzene		19.8		
p,m-Xylene	520	19.8		
o-Xylene	445	13.0		

SURROGATE RECOVERIES:	Parameter	Percent Recovery					
	Trifluorotoluene Bromofluorobenzene	93 % 95 %					

Method: Method 5030, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA, Sept. 1986.

Method 8020, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, Sept. 1986.

ND - Parameter not detected at the stated detection limit.

Comments: San Juan 32-7 # 75

Rold Haiffing Analyst Stacy Wendler
Review

		Remarks						-	10/4/21/17CU	1,1/4/1/				san juan repro Form 578-81
ECORD	ANALYSIS/PARAMETERS	12		7					Received by: (Signa)ure)	Under Companied	Heceived by . (Signature)	Received by: (Signature)	IC. 014 87401	
OF CUSTODY RECORD		to .c	NA Con	7						_	Heceived by	Received by	ENVIROTECH INC. 5796 U.S. Highway 61-3014 Farmington, New Mexico 87401	(505) 632-0615
	J.#75		Sample Matrix	2011					}	170 C			ENVIR 5796 U.S. Farmington,	(50
CHAIN	Project Location	Chain of Custody Tape No.	Lab Number	799le						16.				
	4		Sample Time	0'12/										
	102113	Collins,	Sample Date	John 10/14/5-1					7.	Chris				
	Slient/Project Name	\mathcal{A}	Sample No./ Identification	(1 - 14 moltova					Relinquished by: (Signature)	アプルで	Relinquisfed by: (Signature)	Relinquished by: (Signature)		