

UTE MOUNTAIN UTE 27-44

The following is tabulation of all deviation surveys ran on the Ute Mountain Ute 27-44 well.
The well is located 995' FSL and 1055' FEL (SESE) Sec. (P) 27-31N-14W; MNPM San Juan County, New Mexico.

Depth (Ft.)	Deviation	Depth (Ft.)	Deviation
100'	1/2	2326	7
217	3/4	2419	7
256	1	2514	7 1/2
328	1 1/2	2607	6 1/2
387	2 1/4	2700	7
416	2 1/4	2793	6 3/4
475	2 1/4	2885	7 3/4
563	2 1/2	2948	7 3/4
651	2 3/4	3040	8
743	2 3/4	3134	8
836	3	3228	7 3/4
931	2 3/4	3320	7 3/4
1026	3 1/4	3413	8 1/4
1115	3 3/4	3507	7 3/4
1145	3 3/4	3600	7 1/2
1211	4	3693	7 1/2
1275	4	3723	7 3/4
1338	4 1/4	3818	8
1402	4 1/2	3945	7 3/4
1465	4 3/4	4071	7 3/4
1525	5	4290	7 1/2
1586	5 1/2	4477	7
1676	5 1/4	4601	7
1770	6	4883	7 1/2
1886	6	5068	8
1956	6	5252	8 1/4
2049	6	5501	7
2139	6	5687	7
2234	6 1/2	5860	7

I, Fred J. Clausen, Area Superintendent for Wintershall Corporation, do here by attest that I have inspected the above surveys and found the same to be accurate, valid and complete to the best of my knowledge.



Fred J. Clausen

Area Superintendent

State of Colorado

County Of Montezuma

Subscribed and sworn to me this 11th day of March, 1988


Notary Public

My commission Expires: 06/01/91

