


WELL FILE



RICHMOND PETROLEUM INC.

MILLER 32-6-11 #1
Sec. 11, T32N, R6W
San Juan County, New Mexico

SLOPE TESTS

Depth

230'
750'
1246'
1785'
2265'
2850'

Hole Deviation

1 Degree
3/4 Degree
1 Degree
1 Degree
1 Degree
1 Degree

RECEIVED
OCT 31 1994

OIL CON. DIV.
DIST. 3

State of New Mexico)
) ss
County of San Juan)

I, DANA DEWENTHAL, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Dana Dewenthal
Subscribed and sworn before me this 13th day of August 1990.

Vickie Duran
Notary Public

My Commission Expires 3-17-91.