## UNITED STATES

## DEPARTMENT OF 122 INTERIOR

	Sundry No	tices and Reports on Wells	-	
Type of Well			5.	Lease Number SF-078504 If Indian, All. or Tribe Name
		MAY 200	7.	Unit Agreement Name
Name of Opera	tor	12 00 AT	N	San Juan 32-9 Unit
BURLIA				
RESOUL	RCES OIL	L & GAS COMPANY	8.	Well Name & Number
address 5 Dho	ne No. of Oper	rator	Enstruction 8.	San Juan 32-9 U #285
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700			9.	
			10	30-045-28130 Field and Pool
Location of W	ell, Footage,	Sec., T, R, M , T-32-N, R-10-W, NMPM	10.	Basin Fruitland Coal
1015, 450, 142	0 FWE, BCC.13	, 1 32 11, 11 20 11, 111111	11.	County and State San Juan Co, NM
_X_ Subse	MIRU. ND WH. free. TOOH TIH w/bit. B TOOH w/bit. top @ 3217 80' across	Recompletion Plugging Back Casing Repair	TIH, engage  5 LT&C csg,  3328-70', 3	ction Fracturing off to Injection  Inr hanger & pull  set @ 3582'. Lnr 391-3454', & 3538-
14. 1 hereby	@ 3572′. N	Title Regulatory Admi	orrect.	ate 5/11/00
Signed JAM				ACCEPTED FOR RECU
	Federal or S	tate Office use) Title	Date	ACCEPTED FOR RECO