DEVIATION REPORT

Name of Company Burlington Resources Oil & Gas Company	Address P. O. Box 4289, Farmington, NM 87499	
Lease Name and Number REESE MESA #13	Unit Letter Sec. Twn. Rge.	
Pool and Formation Albino Pictured Cliffs	-1,433 FSL -885 FWL (7) > 13 032N 008W County SAN JUAN	008 W

Depth (Ft.)	Deviation (Degrees)
10	.00
233	2.00
739	2.00
1,232	1.25
1,726	.50
2,286	.50
3,245	.75
3,798	1.75
4,450	1.00



Air Hammer Used? YES / NO



I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for BURLINGTON RESOURCES OIL AND GAS CO., am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 6th day of Dec., 1999

Notary Public In and for San Juan County, New Mexico

My commission expires August 17, 2000