

Key Energy Services, Inc.

Four Corners Division 5651 US Highway 64 P.O. Box 900 Farmington, NM 87499

Phone: 505-327-4935 Fax: 505-327-4962

July 24, 2001

Rig No. 47

Phillips Petroleum Company 5525 Hwy 64 NBU 3004 Farmington, NM 87401

Attn: Patsy Clugston

This letter is to certify that Key Energy Services, Inc., did run deviation surveys at the listed depths on the San Juan 32-7 44M well in S22-T32N-R07W, in San Juan, county, New Mexico.

Depth	Deviation	Depth	Deviation	
156'	3/4°	4575'	M.R.	
310'	3/ <u>4</u> °	4639'	4°	
653'	3/4°	4873'	4³¼°	
1145'	1°	5146'	5° (50)	
1648'	1°	5393'	4° (%) F	AUG 2001
2123'	1/2°	5887'	3½°	7.12.00
2681'	1/4°	6382	3°	
2992'	3/4°	6878'	4° \(\sigma \frac{5}{5}\)	(21 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
3833'	3/4°	7371'	3°	
4367'	21⁄4°	8025'	1¾°	

To the best of my knowledge, I swear this information to be true.

Sincerely,

J.D. Griffith

Drilling contract manager

STAUBLIC

My commission expires: