



Key Energy Services, Inc.

Four Corners Division
P.O. Box 900
5651 US Highway 64
Farmington, NM 87499

Phone: 505-327-4935
Fax: 505-327-4962

November 21, 2000

Koch Exploration Company
P.O. Box 489
Aztec, NM 87410

30-045-30289

This letter is to certify that Key Energy Services did run deviation surveys at the below listed depths on your Cain #1B well, in S20-T31N-R10W in San Juan county, New Mexico.

| Depth | ^m Deviation | Depth | Deviation |
|-------|------------------------|-------|-----------------------|
| 211' | $\frac{3}{4}^{\circ}$ | 2092' | 1° |
| 694' | $\frac{3}{4}^{\circ}$ | 2594' | $\frac{1}{2}^{\circ}$ |
| 1130' | 1° | 2968' | $\frac{1}{4}^{\circ}$ |
| 1637' | $\frac{3}{4}^{\circ}$ | | |

Well drilled from 2980' to 5160' with air hammer .

To the best of my knowledge, I swear this information to be true.

Sincerely,

J.D. Griffith
Drilling contract manager

Notary Public

My commission expires: 12/9/04