(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	JUN 24 1960
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING U.S. GEOLOGICAL SURVEY	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR DURANGO, COLO.	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		**Supplementary Report of Abandonment**	XX

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____ **June 15,** _____, 19 **60**

FOREST - UTE

Well No. __1__ is located **480** ft. from {N / S} line and **1783** ft. from {E / W} line of sec. __34__

SE/4 Sec. 34	**32 N**	**15 W**	**NMPM**
(¼ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)

Wildcat	**San Juan**	**New Mexico**
(Field)	(County or Subdivision)	(State or Territory)

The elevation of the derrick floor above sea level is __5835__ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth 2125'. Completed 9-27-59. Cement Plugs were run as follows: 694-502' with 60 sacks, 1966-1842' with 40 sacks. Erected marker. Well abandoned. Cleaned up and leveled location, completed work on 10-4-59.

RECEIVED
JUN 27 1960
OIL CON. COM.
DIST. 3

I understand that this plan of work must receive approval in writing by the Geological Survey before operation is commenced.

Company ___KERN COUNTY LAND COMPANY___

Address ___226 Petroleum Center Bldg.___

___Farmington, New Mexico___

By ___Original Signed By___
___C. F. Eaton___

Title ___District Engineer___