	(A)	oril 19	52)	
	-			
	•			
M	al l	7		

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Indian Agency	
Marajo - The	
Allottee Mountain	
Loase No. 14-20-4	

SUNDRY NOTICES AND REPORTS ON WELLS SUBSEQUENT REPORT OF WATER SHUT-OFF. NOTICE OF INTENTION TO DRILL SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING NOTICE OF INTENTION TO CHANGE PLANS. SUBSEQUENT REPORT OF ALTERING CASING 1963 NOTICE OF INTENTION TO TEST WATER SHUT-OFF. SUBSEQUENT REPORT OF REDRILLING OR REPAIR. NOTICE OF INTENTION TO REDRILL OR REPAIR WELL SUBSEQUENT REPORT OF ABANDONMENT. NOTICE OF INTENTION TO SHOOT OR ACIDIZE. SURVEY NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO ABANDON WELL Mavajo upa is located ft. from | line and ft. from (State or Territory) (County or Subdivision) The elevation of the derrick floor above sea level is 5730 ft. (****.) DETAILS OF WORK (State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work) It is our intention to drill Well Wo.2 to around 1675' to took Gallup formation. - 7-5/8400 26.46 J-55 Coming - to be comented with 10 socks 00 9.5f J-55 Casing - to be concerted with 75 be I understand that this plan of work must receive approval in writing by the Geological Survey before operations may Company SKELLY OIL COMPANY Address___