


(SUBMIT IN TRIPLICATE)

Indian Agency Nava Jo

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Nava Jo
Lease No. 14-00-403-587



SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 25, 19 59

Well No. 1-32 is located 1080 ft. from N line and 660 ft. from W line of sec. 32
SW 1/4 Sec. 32 32 N. 18 W. N.M.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 5251 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set plugs as follows:

7300-7630 w/40 sx sio set
 5950-6050 w/30 sx sio set
 4600-4700 w/30 sx reg.
 3150-3250 w/30 sx reg.
 2550-2650 w/30 sx reg.
 1300-1400 w/30 sx reg.
 300-260 w/20 sx reg. - bottom surface
 Top surface w/10 sx, 3" drill pipe 4' long above ground with marker.



P & A - May 13, 1959

Location cleaned up and ready for inspection - May 21, 1959.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Compass Exploration, Inc.

Address 1645 Court Place
Denver 2, Colorado

By P. J. Farrelly
P. J. Farrelly
 Title Geologist