

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Contract 11-20-403-912

Allottee Tract 17

Lease No. \_\_\_\_\_

1	2	3	4	5	6	7	8	9	10	11	12

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Subsequent Report of DWT</u>	<u>2</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

NAVJO TRIBE OF INDIANS

FARMINGTON, NEW MEXICO, MARCH 1, 1956

Well No. 1 is located 1980 ft. from S line and 660 ft. from W line of sec. 29  
SW/4 of SW/4 30-N 20-W  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Four Corners Area W/O San Juan New Mexico  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4034 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

DWT No. 1 from 5516' to 5542' with Johnston Tool 1 1/2" top and 1/4" bottom chokes. Tool open one hour. Wash blow for 30 min. then closed. Initial mud 2800#, max. 4 min. fl. 0#, final 2800#. SI after 30 min. 0#. Recovered 10' of gas and oil cut mud. Test Satisfactory.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shale Oil & Refining Company

Address Box 1266

Farmington, New Mexico

By Russell M. Lilly  
Russell M. Lilly  
 Title District Sup.