

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lease No. _____
Unit Ute Mtn. Tribal Lease
#1-22-Ind-2747

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL..... <input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 24, 1946

Well No. 17 is located 700 ft. from N line and 660 ft. from W line of sec. 27

NW 1/4 Sec. 27 32-N 14-W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Barker San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft. Will be furnished later

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is intended to drill a deep test well with rotary equipment to the Pennsylvania Series to a depth of approximately 9500 feet. The following casing program is planned:

400'	-	13-3/8" O.D. Casing	Cemented to top
3000'	-	9-5/8" "	Cemented with 300 sacks cement
9500'	-	7" "	Cemented with 500 sacks cement

GEOLOGICAL SURVEY
RECEIVED

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SOUTHERN UNION PRODUCTION CO.

Address 1104 Burt Building,
Dallas 1, Texas.

Antonia, New Mexico

By Van Thompson

Title Engineer