

(SUBMIT IN TRIPLICATE)

Indian Agency **NAVAJO**
Window Rock, Arizona
Allottee _____
Lease No. **14-20-603-5012**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 17, 1960

Navajo Tribal "B"

Well No. **1** is located **1,910** ft. from **N** line and **1,890** ft. from **E** line of sec. **28**

SW 1/4 of 28
(1/4 Sec. and Sec. No.)

12-N
(Twp.)

17-W
(Range)

(Meridian)

Wilcox

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is **6,019** ft. **G.L.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging, cementing points, and all other important proposed work)

Spotted June 3, 1960.

U. S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

Set **13 1/8"** csg. @ **525'** cemented with **450** cc. cement, circulated **(6-3-60)**.
After **24** hours tested @ **1000'**. Test **O.K.**

RECEIVED
JUN 20 1960

JUN 24 1960
OIL CON. COM.

I understand that this plan of work must receive approval in writing by the Geological Survey before operation may be commenced.

Company **TEXAS PACIFIC COAL AND OIL COMPANY**

Address **P. O. Box 2110**

Fort Worth 1, Texas

By

Title **Manager of Production**