


(SUBMIT IN TRIPLICATE)

Indian Agency **Navajo**
Window Rock, Arizona
Allottee **Navajo Tribe**
Lease No. **14-20-603-3012**



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

NAVAJO TRIBAL "B"

August 9, 1960

Well No. **1** is located **1910** ft. from **[N]** line and **1890** ft. from **[E]** line of sec. **28**
SW 1/4 **28** **32-N** **17-W**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6019** ft. **G.L.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This dry hole was plugged and abandoned as follows:

Set cement plugs: 60 sz. 9200-9100
60 sz. 8975-8875
120 sz. 8550-8380
75 sz. 7900-7750
100 sz. 6900-6700
100 sz. 4400-4200
60 sz. 1780-1635
20 sz. at surface



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **TEXAS PACIFIC COAL AND OIL COMPANY**

Address **P. O. Box 2110**

Fort Worth 1, Texas

By *[Signature]*
Title **Manager of Production**