


Company Southern Union Production Co.

Lease _____ Well No. _____

Sec. 21. T. 32. N., R. 12. W., N.M.P.M.

Location 990' East & 990' North of SW Cor. Sec. 21.
Being in NE $\frac{1}{4}$ SW $\frac{1}{4}$ section 21-32N-12W.

San Juan County New Mexico



Scale—4 inches equals 1 mile.

Natural surface elevation 5983.6

This is to certify that the above plat was prepared from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

Seal:

H. H. Miller

Registered Professional
Engineer and Land Surveyor.

Farmington, New Mexico

Surveyed January 12, 19 50.