



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe, New Mex.**

Lease No. **SF - 078137**

Unit **RECEIVED**

JAN 31 1958
U.S. GEOLOGICAL SURVEY
WASHINGTON, D.C.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 29, 19 **58**

Johns
Well No. **1** is located **660** ft. from **EX** line and **1980** ft. from **EX** line of sec. **20**
SE 1/4 SW 1/4 Sec. 20 **32 N** **13 W** **NMPM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

6162 C.L.

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

12/11-31/57 Drilled to a total depth of 2810. Well temporarily abandoned.

This lease is being assigned to Southern Union Gas Company.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **MONSANTO CHEMICAL COMPANY**

Address **Box 492**

Snyder, Texas

By

Title **E. H. Muhlbach, Dist. Supt.**