



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Jennifer A. Salisbury
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

April 9, 2001

Dolores Silseth
Burlington Res O&G Co
PO Box 4289
Farmington NM, 87499

Re: Barker #22, J-21-32N-14W API 30-045-11334

Dear Ms. Silseth:

The Bradenhead test report on the above well indicates no Bradenhead valve was located. Review Rule 115.B. "Valves shall be installed and maintained in good working order to permit pressures to be obtained on both casing and tubing..." you are hereby directed to bring this well into compliance before July 1, 2001.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely,

Charlie T. Perrin

Charlie T Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC: BLM Farmington
CTP
Well File