


(SUBMIT IN TRIPLICATE)



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Allottee _____

Lease No. **14-20-603-68**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

RECEIVED
AUG 1 1963
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 20, 1963

Well No. **LIZ 1** is located **990** ft. from **N** line and **990** ft. from **E** line of sec. **21**
SE-21 **32 N 19 W** **NMRM**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
MILDCAT **SAN JUAN** **NEW MEXICO**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5134** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The Gallup formation was tested at a depth of 245 ft. No shows of oil, gas or water. Hole will be filled from T.D. to surface with cement, dry hole marker erected.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Frank Yockey**

Address **821 Crestview Dr.**
Farmington, New Mexico

By *Frank Yockey*
Operator
Title _____