



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON  
Governor  
Jennifer A. Salisbury  
Cabinet Secretary

Lori Wrotenbery  
Director  
Oil Conservation Division

April 9, 2001

Dolores Silseth  
Burlington Res O&G Co  
PO Box 4289  
Farmington NM 87499

Re: Barker <sup>Dome</sup>#20, G-21-32N-14W API 30-045-11351

Dear Ms. Silseth:

The Bradenhead test report on the above well indicates no Bradenhead valve was located. Review Rule 115.B. "Valves shall be installed and maintained in good working order to permit pressures to be obtained on both casing and tubing..." you are hereby directed to bring this well into compliance before July 1, 2001.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely,

A handwritten signature in cursive script that reads "Charlie T. Perrin".

Charlie T Perrin  
Deputy Oil & Gas Inspector  
cperrin@state.nm.us

CTP/mk

CC: BLM Farmington  
CTP  
Well File