

(SUBMIT IN TRIPLICATE)

Indian Agency Ute Mountain

UNITED STATES

Tribal Lands

DEPARTMENT OF THE INTERIOR

Allottee _____

GEOLOGICAL SURVEY

Lease No. I-92-Ind-8772

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<u>MAY 27 1963</u>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	<u>U.S. GEOLOGICAL SURVEY</u>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<u>DURANGO, COLO.</u>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Sub. Report of Plug Back</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 13, 19 63

Well No. 8 is located 1750 ft. from N line and 940 ft. from W line of sec. 15

SW Section 15
(1/4 Sec. and Sec. No.)

32-N
(Twp.)

14-W.
(Range)

T.M.P.M.
(Meridian)

Creek
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6538 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was plugged back in the following manner;

1. Set C.I. Bridge Plug @ 8750'.
2. Spot 9' Hydramite plug from 8741' to 8750'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 990

Farmington, New Mexico

By ORIGINAL SIGNED E. S. OBERLY
Title Petroleum Engineer