

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

RECEIVED
FEB 26 1997
Bureau of Land Management
Durango, Colorado

1. Type of Well
GAS

RECEIVED
MAR - 5 1997

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

OIL CON. DIV.
DIAL 5

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

2708' FSL, 1608' FWL, Sec. 16, T-32-N, R-14-W, NMPM

F

5. Lease Number
I-22-IND-2772
6. If Indian, All. or
Tribe Name
Ute Mountain Ute
7. Unit Agreement Name

8. Well Name & Number
Ute #12
9. API Well No.
30-045-11426
10. Field and Pool
Barker Dome Paradox
11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other -	

13. Describe Proposed or Completed Operations

12-28-96 MIRU. ND WH. NU BOP. TIH, release Model "R-3" pkr. TOO H w/2 7/8" tbg.
12-29-96 TOO H w/pkr. TIH w/7" csg scraper to 8590'. Attempt to circ out pkr fluid.
Blow well & CO w/N2 to 8680'.
12-30-96 Blow well & CO. TOO H w/csg scraper. TIH, CO to PBTD @ 8784'. Blow well &
CO.
12-31-96 Blow well & CO.
1-1-97 Blow well & CO. TIH w/268 jts 2 7/8" 6.5# L-80 tbg & Model "R-3" pkr; landed
tbg @ 8623'; set pkr @ 8420'. ND BOP. NU WH. Blow well & CO. RD. Rig
released.
1-11-97 MIRU. Fish for sandline. Can not pull mandrel free. Fishing. SDON.
1-12-97 ND WH. NU BOP. Release pkr. TOO H w/pkr & tbg. Mandrel stuck in "F" nipple.
TIH w/Model "R-3" pkr & 262 jts 2 7/8" 6.5# L-80 tbg. ND BOP. NU WH. Swabbin
RD. Rig released.
1-13-97 Swab well.
1-17-97 RU. TIH w/1 1/4" coiled tbg. Land tbg in hanger. Cut tbg. Tbg fell through
slips. TIH w/fishing tools. Tag top of fish @ 236'. SDON.
1-18-97 Pull fish to surface. TOO H. TIH w/1 1/4" coiled tbg to 8540'. Cut tbg. RD.

Continued on back

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 2/24/97

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

ACCEPTED FOR FLOPO

By: [Signature] 2-24-97

For: [Signature]

Bureau of Land Management

1-19-97 Circ hole clean w/180,000 SCF N2. Blow well & CO.

1-20/22-97 Blow well & CO. RD. Rig released.

2-22-97 MIRU. ND WH. NU BOP. Release pkr. TOOH w/pkr & 2 7/8" tbg. TIH w/pkr & install gas lift mandrels in 2 7/8" tbg @ 4975', 6040', 6837', 7493', 7949'. Reset pkr @ 8568' Reland 2 7/8" tbg @ 8641'. ND BOP. NU WH. RD. Rig released.