UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	I- 22 IND 2772
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
azozodione dontzi	Ute_Indian
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas ry	Ute
well Well other	9. WELL NO.
2. NAME OF OPERATOR	4
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Barker Creek- Paradox
3. ADDRESS OF OPERATOR	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 10, T32N, R14W
AT SURFACE: 540'/S, 1980'/W	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan New Mexico
	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT. OR OTHER DATA	15 ELEVATIONS (SHOW DE KDS AND WD)
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7100' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
rest water shut-off	
FRACTURE TREAT	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
MULTIPLE COMPLETE	
CHANGE ZONES U U ABANDON*	
(other) Current Status	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent. Approval is requested to retain this well in abandoned status. This area is being evaluated for a Gas Storage	irectionally drilled, give subsurface locations and it to this work.)* i its present temporarily
Subsurface Safety Valve: Manu. and Type	Ft.
18. I hereby contify that the foregoing is true and correct Div. Producti SIGNED TITLE Engineer	.on date9=20=78
(This space for Federal or State off	
APPROVED BYTITLETOWNS OF APPROVAL, IF ANY:	DATE!!!
	SEP 2 5 1978

Take