

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF-078146

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Newberry "B"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 35, T32N, R12W

12. COUNTY OR PARISH

San Juan

13. STATE  
New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Tenneco Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 1714, Durango, Colorado

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1070 FNL 1450 FWL Unit C

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6343 Gr.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Rigged up completion unit 9/10/66. PBTD 7553'. Perforated 7520-30, 7488-91, with 6 holes. Frac with 40,000# sand and 35,000 gals. water. Set bridge plug at 7470. Perf. 7439-42, 7428-31, 7417-20 with 6 holes. Frac with 40,000# sand and 35,000 gals. water. Set bridge plug at 7390. Perf. 7352-56 with 5 holes, 7341-47 with 8 holes, 7331-35 with 5 holes. Frac with 40,000# sand and 35,000 gals. water. Cleaned out to 7553. Ran 2 3/8" EUE tubing, set at 7520.

Released rig 9/12/66.  
Waiting on test.

RECEIVED

SEP 15 1966

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

RECEIVED

SEP 16 1966

OIL CON. COM.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Harold C. Nichols

TITLE Senior Production Clerk

DATE 9/14/66

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

## DISTRIBUTION:

5-USGS, 1-Continental, 1-Atlantic, 1-File

\*See Instructions on Reverse Side