UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR Verse side)

Form approved. Budget Burecu No. 42-R1424.

5. LEASE DESIGNATION AND ESCIAL NO.

GEOLOGICAL SURVEY			14-20-604-5546	1
SUNDRY (Do not use this form Use	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
OIL GAS WELL OTHER			7. UNIT AGREEMENT NAME	
NAME OF OPERATOR			8. FARM OR LEASE NAME	
Aztec Oil & Gas Company			Middle Canyon	
ADDRESS OF OPERATOR	9. WELL NO.			
P. O. Drawer 570, Farmington, New Mexico			#1	
Location of WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1600 FSL & 2500 FWL, Section 14-32N-15W			10. FIELD AND POOL, OR WILLDAT Undesignated Dahota II. L.S., T., P., M., OLDER, AND	
4. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)		Section 14-32N-15W	
	Lade Anaramaia Pau Ta lediana	Name of Name Parest or I	San Juar	<u>ow l'exi</u>
check Appropriate box to indicate france of fronce, kepon, o			EQUENT REPORT OF:	
	OF INTENCION TO:	SUBSEC	CODE MAIORI OF .	
	POLL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
NOTICE				
NOTICE	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
TEST WATER SHUT-OFF FRACTURE TREAT	PULL OR ALTER CASING MULTIPLE COMPUNE	WATER SHUT-OFF PRACTULE TREATMENT SMOOTING OR ACIDIZING (Other)	REPAIRING WELL ALTERING CASING	X

- (1) Spotted plug from TD to 3200' with 20 sacks cement.
- (2) Shot off. Pulled 1125' of 4-1/2" 10.5# casing.
- (3) Spotted plug from 1200' to 1050'.
- (4) Spotted 50' plug from 275' to 325'.
- (5) Spotted plug from 125' to surface.
- (6) Cleaned location & installed dry hole marker. Plug & Abandon.





JUL 1 1971

U. S. GEOLOGICAL SURVEY DURANGO, COLO.

18. I hereby certify that the foregoing is true and correct	TIPLE District Superintendent	pare Jung 1
'(This space for Federal or State office use)		And the second s
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TIPLE	Dige

2/1