

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Form Approved.  
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐  
well well
2. NAME OF OPERATOR  
AMOCO PRODUCTION COMPANY
3. ADDRESS OF OPERATOR  
501 Airport Drive Farmington, NM 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
1840' FSL x 1180' FWL, Section 13,  
AT SURFACE: T32N, R14N  
AT TOP PROD. INTERVAL: Same  
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO: |                          | SUBSEQUENT REPORT OF: |                                     |
|--------------------------|--------------------------|-----------------------|-------------------------------------|
| TEST WATER SHUT-OFF      | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| FRACTURE TREAT           | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| SHOOT OR ACIDIZE         | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| REPAIR WELL              | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| PULL OR ALTER CASING     | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| MULTIPLE COMPLETE        | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| CHANGE ZONES             | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| ABANDON*                 | <input type="checkbox"/> |                       | <input checked="" type="checkbox"/> |
| (other)                  |                          |                       |                                     |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

As a result of the above well being unable to produce commercial quantities of gas, it was plugged and abandoned on 5/23/79 as follows:

- 1) Squeezed perforations at 3086'-3088' and 3135'-3143' and spotted 50' cmt plug with 150 sx Class "B" Neat cmt.
- 2) Spotted 100' plug above top of Gallup zone from 2350'-2450' with 10 sx Class "B" Neat cmt.
- 3) Spotted 30' plug from 0' to 30' with 5 sx Class "B" Neat cmt.
- 4) Erected abandonment marker and cleaned up location.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_

18. I hereby certify that the foregoing is true and correct

SIGNED \_\_\_\_\_ TITLE Dist. Adm. Supvr. DATE 6/7/79

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

5. LEASE	M00-C-1420-1729
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	Ute Mountain Tribe
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME	Ute Mountain Tribal "O"
9. WELL NO.	1
10. FIELD OR WILDCAT NAME	Ute Dome Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	NW/4 SW/4 Section 13, T-32-N, R-14-W
12. COUNTY OR PARISH	San Juan
13. STATE	NM
14. API NO.	30-045-23237
15. ELEVATIONS (SHOW DF, KDB, AND WD)	6777' GL, 6787' KB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

