

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐

2. NAME OF OPERATOR
AMOCO PRODUCTION COMPANY

3. ADDRESS OF OPERATOR
501 Airport Drive Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
1160' FNL x 790' FEL, Section 26,
AT SURFACE: T32N, R15W
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) Completion <input type="checkbox"/>	

5. LEASE
MOO-C-1420-1732

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Ute Mountain Tribe

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Mountain Ute Tribal "B"

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
NW/4 NE/4 Section 26, T32N, R15W

12. COUNTY OR PARISH
San Juan

13. STATE
NM

14. API NO.
30-045-23542

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6687' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Completion operations commenced on 8/25/79. Circulated out hole and pressure tested to 3800#; held OK. Spotted 200 gallons 15% HCL water.

Perforated from 3234-3242', 3264-3270' and 3288-3294' with 2 SPF. Sand-water fraced with 81,000 gallons frac fluid and 140,000# sand.

Swabbed well and released completion rig on 9/10/79.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct


SIGNED _____ TITLE Dist. Adm. Supvr. DATE _____

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



SEP 19 1979

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.