

P

30-045-23636

6-25-79

NSL-1054
F. Loc. 820/S; 2220/W Elev. 5829 GL Spd. 6-11-80 Comp. 10-23-80 TD 6980 PB 6932

Casing S. 85/8 @ 257 W 250 Sx. Int. @ W Sx. Pr. 5/12 @ 6963 W 1300 Sx. T. 1/12 @ 6699
Csg. Perf. Prod. Stim. SWF

TRANS
R

6714-6915
1184 40F
I.P. 1142 MCF/D After Hrs. SICIP 1500 PSI After 7 Days GOR Grav. 1st Del. 12-31-80 \$

TOPS	NITD	Well Log	TEST DATA						
Kirtland	C-103	Plat	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland	C-104 5-11-81	Electric Log	2/16/81	917	126	337	459	113	6570
Pictured Cliffs	2060 3-3-81 1/4	C-122	7/16/81	742	58	366	371	58	
Cliff House	3710 Ditr 3-16-81	Dfa 12-31-80	4/16/82	630	40	383	315	46	
Menefee	Datr	Dac	4/8/83	NSP					
Point Lookout	MC 2801								
Mancos	7/23/93 NIT P4H 1-25-94 NIT Recor p. Fict. Coal 9 plug DAK. + NIV. Zone ABAND. 3-16-94								
Gallup									
Sanostee									
Greenhorn									
Dakota			6684						
Morrison	Synder Oil Corp. Columbia Energy Corp. Consolidated O&G								
Entrada			S/320						

P
O
I.

Basin Dak Co. SJ S 34 T 32NR 13W U N Oper. Hallwood Pet. Inc. Lse. Robinson Bros No. 1M

P

30-045-23636

6-25-79

NSL-1054
F. Loc. 820/S; 2220/W Elev. 5829 GL Spd. 6-11-80 Comp. 10-23-80 TD 6980 PB 6932

Casing S. 85/8 @ 257 W 250 Sx. Int. @ W Sx. Pr. 5/12 @ 6963 W 1300 Sx. T. 1/14 @ 4585
Csg. Perf. Prod. Stim. SWF

TRANS
SUG
GR

4536-4757
939 40F
I.P. 788 MCF/D After Hrs. SICIP 1185 PSI After 14 Days GOR Grav. 1st Del. 12-31-80 \$

TOPS		NITD	Well Log	TEST DATA						
Kirtland		C-103	Plat	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland		C-104	Electric Log	2/16/81	787	125	333	636	67	1589
Pictured Cliffs	2060	5-31-81	C-122	7/16/81	641	64	358	513	39	
Cliff House	3710	Ditr 3-16-81	Dfa	4/16/82	607	39	382	486	26	
Menefee		Datr	Dac	5/29/84	587	23	404	497	14	
Point Lookout			MC 2801	2/5/86	602	19	373	421	17	
Mancos										
Gallup										
Sanostee										
Greenhorn										
Dakota	16684									
Morrison										
Entrada										

P
O
I.

Blanco MV Co. SJ S 34 T 32NR 13W U N Oper. Hallwood Pet. Inc. Robinson Bros No. 1M