## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Form 9–331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF-078312
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a difference of the sum of the su	
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas rg	Hubbard
well well other	9. WELL NO.
2. NAME OF OPERATOR	6
Southland Royalty Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco Pictured Cliffs
P.O. Drawer 570, Farmington, N.M. 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.)	Section 15, T32N, R12W
AT SURFACE: 790' FSL & 1760' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTI	CE,
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
PROUEST FOR APPROVAL TO: CURSTOLIENT REPORT OF	60.90 GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion of zend
PULL OR ALTER CASING	change on Form 9–370.) 5
MULTIPLE COMPLETE	MAR 12 281
CHANGE ZONES U U 0.0 SANDON*	OIL CON. COM.
(other) Snud and Casing Report Y	JOIN ONLY

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded 12-1/4" surface hole at 1:00 P.M. 2-25-81 and drilled to a 2/25/81 Total Depth of 154'. Ran 3 joints (135.87') of 8-5/8", 24#, K-55 casing set at 147'. Cemented with 115 sacks of Class "B" with 1/4# flocele per sack and 3% CaCl<sub>2</sub>. Plug down at 5:45 P.M. 2-25-81. ACCEPTED FOR RECORD Cement circulated to surface.

MAR 1 0 1981

Subsurface Safety Valve: Manu. and Type _		FARMINGTON DISTRICT BY Set @	Ft.
18. I hereby certify that the foregoing is tru signed Signed	e and correct TITLE Drilling C	lerk DATE February 26, 1981	
	(This space for Federal or State	e office use)	
APPROVED BY	TITLE	DATE	