

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**OIL CONSERVATION DIVISION**

**DISTRICT I**  
P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-045-25930
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B111-24, E284-11, & F8445
7. Lease Name or Unit Agreement Name Wright State Com
8. Well No. 1E
9. Pool name or Wildcat Wildcat GL/Basin Dakota

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Taurus Exploration, U.S.A., Inc.	
3. Address of Operator 2198 Bloomfield Highway; Farmington, NM 87401	
4. Well Location Unit Letter <u>I</u> : <u>1550</u> Feet From The <u>South</u> Line and <u>790</u> Feet From The <u>East</u> Line Section <u>36</u> Township <u>32 North</u> Range <u>13 West</u> NMPM San Juan County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5789	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Downhole Commingle ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Per DHC-1844 This well was downhole commingled as follows:

3/30/98 MIRU. TOH with Gallup tubing.  
3/31/98 Dakota tubing stuck. Run freepoint and cut off tubing above packer. TOH.  
4/1/98 TIH with fishing tools. Jar seal assembly loose. TOH.  
4/2/98 Mill out Baker model D packer. TOH.  
4/3/98 Ran 221 joints 2 3/8" 4.7# tubing set at 6875' seating nipple at 6845'. Nipple up wellhead and rig down.

RECEIVED  
APR - 8 1998

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gary W. Brink TITLE Production Superintendent DATE 4/6/98  
TYPE OR PRINT NAME Gary W. Brink TELEPHONE NO. 505-325-6800

(This space for State Use)

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT # 3 DATE APR - 8 1998  
CONDITIONS OF APPROVAL, IF ANY: