

F

30-045-25946

4-16-84

F. Loc. 1790/S; 1090/E Elev. 6340 GL Spd. _____ Comp. _____ TD _____ PB _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. I. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas _____
 I.P. _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS		NiTD X	Well Log	TEST DATA						
			Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.
Ojo Alamo		C-103								
Kirtland		C-104	Electric Log							
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfa							
Chacra		Datr	Dac							
Cliff House		Acres S/320								
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										

P
o
o

Basin Dak. Co. SJ S 35 T 32N R 11W U I Oper. Southland Royalty Co. Lse. Horton

No. 3

Horton #3

I-35-32N-11W

SOUTHLAND ROYALTY COMPANY

Caller Service 4104
Farmington, New Mexico 87491

DEC 20 1985

CERTIFIED--RETURN RECEIPT REQUESTED

Loullane Royalty Company
P. O. Drawer 570
Farmington, NM 87402

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 3 Horton, NE/4SE/4 sec. 35, T. 32 N., R. 11 W., San Juan County, New Mexico, lease 95-081240. As discussed with your Company representative on December 19, 1985, the subject APD is rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 15 days, we will presume that no construction occurred. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely,

/s/ J. Stan McKee

 J. Stan McKee
Area Manager

Enclosure

cc:
12000

ABANDONED LOCATION

DEC 26 1985

1. DIV
1113