

# MERRION

OIL & GAS

## HAVASU No. 1


Section 22, T32N, R13W  
San Juan County, New Mexico

### SLOPE TESTS

	<u>Depth</u>	<u>Hole Deviation</u>
#1	100'	.75°
#2	209'	.75°
#3	290'	.75°
#4	390'	.75°
#5	490'	5°
#6	590'	1°
#7	690'	.75°
#8	790'	1-1/2°
#9	887'	2°
#10	1007'	3°
#11	1107'	3-1/2°
#12	1207'	4°
#13	1265'	4°


RECEIVED  
SEP 11 1997  
OIL CON. DIV.  
DIST. 3

I, Steven S. Dunn, being first duly sworn, depose and state that the attached and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

  
Steven S. Dunn

Subscribed and sworn before me this 9th day of September, 1997

State of New Mexico     }  
                                      } ss  
County of San Juan     }

  
Esther J. Greyeyes  
Notary Public

My Commission Expires: August 7, 1998