

MERRION

OIL & GAS

DOWN SET 1-29-12 HIKE No. 1

Section 1, T29N, R12W
San Juan County, New Mexico


SLOPE TESTS

RECEIVED
OCT 12 1994
OIL CON. DIV.
DIST. 8


<u>No.</u>	<u>Depth</u>	<u>Hole Deviation</u>
1	265'	1/4°
2	755'	1/2°
3	1253'	1/2°
4	1560'	1/2°
5	2065'	1/4°
6	2561'	1/4°
7	3059'	1/2°
8	3559'	1/2°
9	3840'	1/4°

State of New Mexico }
 } ss
County of San Juan }

I, Steven S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.



Subscribed and sworn before me this 11th day of October, 1994


Esther J. Greeyes
Notary Public

My Commission Expires: August 7, 1998