

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. _____

Unit _____

San Juan 3-5 Unit Area

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|---|---|
| NOTICE OF INTENTION TO DRILL..... | SUBSEQUENT REPORT OF WATER SHUT-OFF..... |
| NOTICE OF INTENTION TO CHANGE PLANS..... | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... | SUBSEQUENT REPORT OF ALTERING CASING..... |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL..... | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR..... |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... | SUBSEQUENT REPORT OF ABANDONMENT..... |
| NOTICE OF INTENTION TO PULL OR ALTER CASING..... | SUPPLEMENTARY WELL HISTORY..... |
| NOTICE OF INTENTION TO ABANDON WELL..... | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 9,

19 57

Well No. 1-10 is located 1850 ft. from N line and 1100 ft. from W line of sec. 10
34 1/2 Sec. 10 34 1/2 34 1/2 34 1/2
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Albany San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 7563 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud: 6-19-57. At TD of 205' set 8-5/8" - 192' w/105 Sct. (circulated)
Pipe is 8-5/8" OD Sct. 2 1/2' Hw. size hole 2 1/2". 800 36 lbs. nipple-up
Tested casing to 500'. Shut-off OK, drilled plug. sig. 2910' shale

ILLEGIBLE



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

L. H. J. HARRIS

Company _____

Address _____

Old Roswell Pet. Bldg.

Roswell, New Mexico

By _____

Title _____