



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office Santa Fe, N.M.

Lease No. SF 078939-D

Unit _____

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 28, 1958

Well No. 3 is located 1650 ft. from N line and 1650 ft. from W line of sec. 17

SW $\frac{1}{4}$ Sec. 17 19N 4W N.M.P.M.
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Sandoval New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6675 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Mudded open hole up into 7" casing shot 7" casing at 800'; put 30 sack cement plug in top of 7" casing; at 800' pulled 7" casing filled hole with mud and put plugged top of surface and set pipe marker with 10 sacks cement.
31' - 12 $\frac{1}{2}$ " casing left in hole.
842' - 7" casing left in hole; finished plugging February 12, 1958.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ed W. Cannedy

Address 618 Central Ave., SE

Albuquerque, New Mexico

By Ed W. Cannedy
Ed W. Cannedy
Title Operator

