

COPY FOR
STATE OF NEW MEXICO
**OIL CONSERVATION
COMMISSION**
SUBMIT IN TRIPLICATE TO
DISTRICT OFFICE

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Land Office _____
Lease No. _____
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 17, 1952

Well No. 1 is located 1650 ft. from N line and 1650 ft. from W line of sec. _____

S. 4 Sec. 27 (Sec. and Sec. No.) 26N (Twp.) 11W (Range) 111-1-2 (Meridian)
11-1-2 (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6280 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

This well was plugged, with a plug of 35 bags of cement on bottom, displaced with 19 barrels of mud. Got a full up of 117 feet. Pulled up in surface pipe and set a plug with 10 bags of cement. Cemented a marker in top of surface pipe. 1 1/2" in pipe 3 ft. above ground level.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Boyd H. Smith

Address 1110 1/2 W. Main Bldg.

Richita Falls, Texas

By _____

Title Tool Pusher