

STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION

DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 081028-A
Unit Flood #1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 Flood is located 990 ft. from XXK line and 990 ft. from E line of sec. 24
SE SE Sec. 24 26 N 13 W N. M. P. M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6111 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded June 13, 1951 with cable tools. 100 ft. of 8-5/8" was cemented with 100 sacks, on June 21, 1951 Rotary moved on July 7th and the plug was drilled July 8, 1951 The fluid level was checked for two hours with 750# pressure, with no drop. Casing test O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SULLIVAN & HILL
Jack Sullivan, Operator
 Address 341 North Foothill Road
Beverly Hills, Calif.

By R. D. Young
 Title Agent

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
UNITED STATES
(SUBMIT IN TRIPLICATE)

[illegible]

SUNDRY NOTICES AND REPORTS ON WELLS

(INDICATE ABOVE BY CHECKING NATURE OF REPORT, NOTICE OR OTHER DATA)	
☐	NOTICE OF INTENTION TO ABANDON WELL
☐	NOTICE OF INTENTION TO TULL OR ALTER CASING
☐	NOTICE OF INTENTION TO SHOOT OR BLOWHOLE
☐	NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL
☐	NOTICE OF INTENTION TO TEST WATER SHUT-OFF
☐	NOTICE OF INTENTION TO CHANGE PLANS
☐	NOTICE OF INTENTION TO DRILL
☐	SUPPLEMENTARY WELL HISTORY
☐	SUBSEQUENT REPORT OF ABANDONMENT
☐	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
☐	SUBSEQUENT REPORT OF ALTERING CASING
☐	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
☐	SUBSEQUENT REPORT OF WATER SHUT-OFF

1 Flood is located _____
_____ ft. from _____ line and _____
_____ ft. from _____ line of sec. _____
_____ M. B. N. _____
_____ (M. B. N. _____)
_____ New Mexico _____
_____ (State or Territory) _____
_____ (County or Subdivision) _____
_____ (City or Town) _____
_____ (Post Office) _____
_____ (Section) _____
_____ (Range) _____
_____ (Township) _____
_____ (County) _____
_____ (State) _____

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

State names of and expected depths to objective sands; show area, weight, and length of proposed casing; indicate mudlogging jobs, cementing points, and all other important proposed work

[illegible]

1 and noted that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Name _____
Address _____
City _____ State _____ Zip _____

By _____
R. D. Young
Title _____