Budget Bureau 42-R358.2. Approval expires 12-31-52.

Land Office Santa Pa

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS	
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING.	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
(Indicate above by Check Mark	NATURE OF REPORT, NOTICE, OR OTHER DATA)
DOUTHIT Well No. 1 is located 220 ft. fro	om S line and 990 ft. from E line of sec. 8
N. E. 1/4 Sec. 3 T-27-N R-1 (W 860, and 860, No.) (Twp.)	(Kange) (Maridian)
Wildcat San Juan- (Field) County	New Mexico
(Field) (County	or Subdivision) (State or Territory)
The elevation of the derrick floor above sea level is 5935 ft. G. L. DETAILS OF WORK (State names of and expected depths to objective sands; show sizes, weights, and longths of proposed easings; indicate mudding jobs, comenting points, and all other important proposed work)	
10-3/4" and 79 Jts (2501') of 7" co 2525' to 2600' in 7" stub with 25 s in top of 10-3/4" stub, top of 13-3 was embedded in cement with 4' abov location cleaned up.	clows: 1-Jt (31') of 13-3/8", 2-Jts (41') of sing. Cement plugs were spotted as follows: sacks, and cement plugs were installed 8/8" stub and at surface. 10' of 4" pipe to ground level, well sign installed and
Well permanently abandoned 12/3/52.	DEGETVE D
	DEC 1.1 1952
I understand that this plan of work must receive approval i	IJ. C. <u>GEOLOGICAL SURVEY</u> n writing by the Geological Survey before operations may be commenced.
Company Delhi Oil Corporation	
Address Box 1175	
Farmington, New Mexico	By Proceeding
	Title Superintendent